## **CDM Project Development Roadmap**

Step 1: Scope 2-4 weeks

Prepare a scoping document such as a Project Information Note (PIN).

This can usually be done by yourself.



Step 2. **Design** 6-8 weeks

Prepare a Project Design Document (PDD). You may require assistance to do this.



Step 3. **Validation** 8-10 weeks

Have the PDD independently assessed by a Designated Operational Entity (DOE) and at the same time request a Letter of Approval from Designated National Authority (DNA).



Step 4. **Registration** 8-16 weeks

Submit the PDD (via the DOE that you have chosen) to the Clean Development Mechanism Executive Board (CDM EB).



Step 5. **Monitoring** Quarterly

Monitor and evaluate the projects performance in accordance with the PDD you have prepared and submitted to the CDM EB.



Step 6. **Verification** 6-8 weeks

Ask for written assurance that your CDM project has acheived greenhouse gas emission reductions from the DOE you have chosen.



Step 7. **Issuance** 2 weeks

Once you have recieved certification for your project from the CDM EB, you may then request that they issue you the associated CERs for the project.